

Translations:Fusion welding of optical fibres/24/en

After shrinking, position the smooove on the cooling plate before welding other fibres. Then place the smoooves in the cassette and wind the fibres.