

# Translations:Fusion welding of optical fibres/5/en

---

Strip 3/4 cm of the fibre. Clean the bare fibre with isopropyl alcohol before cleaving.